	Type	Hits	Search Text	DBs	Time Stamp
1	IS&R	509	(164/440).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/07/13 13:10
2	IS&R	266	(164/490).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/07/13 13:02
3	IS&R	373	(164/444).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/07/13 13:03
4	IS&R	325	(164/486).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/07/13 13:03
5	IS&R	136	(164/268).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/07/13 13:04
6	IS&R	316	(164/472).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/07/13 13:04
7	IS&R	177	(164/487).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/07/13 13:04
8	IS&R	28482	("164").CLAS.	US-PGPUB; USPAT	2006/07/13 13:10
9	BRS	462	S8 and (((continuous$2 near3 cast$3) near20 mold) near50 (cool$3 or water or oil or gas)).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/07/13 13:12

	Type	Hits	Search Text	DBs	Time Stamp
10	BRS	80	S8 and ((((continuous$2 near3 cast$3) near20 mold) near50 (cool$3 or water or oil or gas)) near50 (annul$2 or sect$4)).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/07/13 13:12
11	BRS	51	S8 and ((((continuous$2 near3 cast$3) near10 mold) near20 (cool$3 or water or oil or gas)) near20 (annul$2 or sect$4)).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/07/13 13:14
12	BRS	1	S8 and ((((continuous$2 near3 cast$3) near10 mold) near20 horizontal near20 (cool$3 or water or oil or gas)) near20 (annul$2 or sect$4)).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/07/13 13:15
13	BRS	15	S8 and ((((continuous$2 near3 cast$3) near10 mold) near20 horizontal near20 (cool$3 or water or oil or gas))).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/07/13 13:15

	Type	Hits	Search Text	DBs	Time Stamp
14	BRS	16	((((continuous$2 near3 cast$3) near10 mold) near20 horizontal near20 (cool$3 or water or oil or gas))).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/07/13 13:16
15	BRS	2	((((continuous$2 near3 cast$3) near10 mold) near20 horizontal near20 (cool$3 or water or oil or gas) near50 (nozzle$1 or valve$1 or plug$1 or sect$4))).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/07/13 13:17